

CUTTING SAMPLE DESCRIPTIONS.

PELICAN-1.

APW

13/4/70.

INTERVAL.	%	DESCRIPTION.
8660-70	10%	<u>SILTSTONE</u> . aa
	10%	<u>COAL</u> . aa
	80%	CEMENT CAVINGS.
8670-80.	10	<u>SILTSTONE</u> aa
	Tr	<u>SANDSTONE</u> . wh. fq. ws. sa-sr hd. tigr. no show.
	90%	CEMENT CAVINGS.
8680-90.	100 50.	CEMENT CAVINGS.
	50	<u>SILTSTONE</u> md. bn firm-soft mic.
8690-8700	70.	<u>SILTSTONE</u> AA.
	30	CEMENT CAVINGS.
8700-10.		AS ABOVE.
8710-20.		AS ABOVE. Believe siltstone washing away thru shaker & sieve
8720-30.		AS ABOVE.
8730-40.	100	<u>SILTSTONE</u> . AA. SAMPLES VERY CONTAMINATED WITH CEMENT. BUT
8740-50	70	<u>SILTSTONE</u> . POOR RETURNS. - WASHING AWAY. INTERPRET AS
	30	<u>COAL</u> . SOFT MUDSTONE.
8750-60	50.	<u>SILTSTONE</u> .
	50	<u>MUDSTONE</u> .
8760-8800.		AS ABOVE.
8800-8810.	70.	<u>SILTSTONE</u> .
	30	<u>COAL</u> .
8810-20.		AS ABOVE.