

STRUCTURE

Structural closure is based on regionally spaced dip lines and a single strike line. Part of the lower closure is dependent on the presence of a poorly controlled north trending fault. Structurally the lead is very similar to the already drilled Pelican 4 structure. Structural risk is ranked as moderate.

ADDITIONAL WORK REQUIREMENTS

Survival was not addressed in the Rocky Cape Seismic Survey. Additional seismic data is required to investigate this lead.