

Line Log

Line Name: SS04-001-009

Start Of Line: 17/01/2005 08:54:30

Shotpoint	Log Time	Message
1001	17/01/2005 08:55:47	LINE START - SS04-001-009 shot 1001 time 1-17-2005 8:54:30.205819
1009	17/01/2005 08:55:48	SOL String pressures 1:2054.5 PSI 2:2019.7 PSI 3:2016.2 PSI
	17/01/2005 08:55:48	Volume source 1 3040 cu in (ideal volume 3040)
	17/01/2005 08:55:49	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	17/01/2005 08:55:49	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	17/01/2005 08:55:49	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1009, 8714, '1-17-2005 8:55:44.936806')
	17/01/2005 08:55:50	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	17/01/2005 08:55:50	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	17/01/2005 08:55:50	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1009, 8714, '1-17-2005 8:55:44.936806')
	17/01/2005 08:55:50	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	17/01/2005 08:55:50	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	17/01/2005 08:55:50	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1009, 8714, '1-17-2005 8:55:50.375000')
	17/01/2005 08:55:50	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	17/01/2005 08:55:50	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	17/01/2005 08:55:50	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1009, 8714, '1-17-2005 8:55:44.936806')
	17/01/2005 08:55:50	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	17/01/2005 08:55:50	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	17/01/2005 08:55:50	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1009, 8714, '1-17-2005 8:55:44.936806')
	17/01/2005 08:55:51	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	17/01/2005 08:55:51	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	17/01/2005 08:55:51	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1009, 8714, '1-17-2005 8:55:44.936806')
	17/01/2005 08:55:51	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	17/01/2005 08:55:51	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	17/01/2005 08:55:51	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1009, 8714, '1-17-2005 8:55:44.936806')
	17/01/2005 08:55:51	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	17/01/2005 08:55:51	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key

Line Log: SS04-001-009 (continued)

Shotpoint	Log Time	Message
	17/01/2005 08:55:51	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1009, 8714, '1-17-2005 8:55:44.936806')
1035	17/01/2005 08:59:56	tcucom - main: Lost sync with TCU - didn't see CR when expected - %GD096 looking for 102 got 17 plus 'S'
1036	17/01/2005 08:59:59	LOST SHOT - Failed to see arm from TCU
1045	17/01/2005 09:01:33	adread - li_write: write 1 bytes to fd 13 failed... Error cause: (4) Interrupted system call
1046	17/01/2005 09:01:34	LOST SHOT - Failed to detect T0 from Nodes
1398	17/01/2005 09:58:03	adread - li_write: write 1 bytes to fd 13 failed... Error cause: (4) Interrupted system call
1399	17/01/2005 09:58:04	LOST SHOT - Failed to detect T0 from Nodes
1718	17/01/2005 10:49:04	String_2 Cluster_2 Gun_4 (300 cu in) fired 1.7 mS late.
1739	17/01/2005 10:52:27	String_2 Cluster_2 Gun_4 (300 cu in) fired 1.7 mS late.
2887	17/01/2005 13:58:07	tcucom - process_tcu_message: Common clock was 1000 milli seconds fast
2889	17/01/2005 13:58:17	tcucom - process_tcu_message: Common clock was 1010 milli seconds slow
2890	17/01/2005 13:58:29	tcucom - process_tcu_message: Common clock was 1010 milli seconds slow
2891	17/01/2005 13:58:41	tcucom - process_tcu_message: Common clock was 1010 milli seconds slow
3441	17/01/2005 15:38:18	String_1 Cluster_1 Gun_2 (250 cu in) fired 1.1 mS late.
3615	17/01/2005 16:11:26	Timeout on message read from Navigation system
	17/01/2005 16:11:27	END OF LINE SS04-001-009 shot 3615 time 1-17-2005 16:11:2.897819
	17/01/2005 16:11:27	EOL String pressures 1:2078.8 PSI 2:2038.0 PSI 3:2034.5 PSI
	17/01/2005 16:11:27	EOL Volume source 1 3040 cu in.
	17/01/2005 16:11:45	Operator Command SHOT DISABLE
		Totalshots on line = 2607 Shots with one or more errors 2 (0.1%)
		Shots with bad timing 2 (0.1%)