

Line Log

Line Name: SS04-007-017

Start Of Line: 19/01/2005 17:24:32

Shotpoint	Log Time	Message
1001	19/01/2005 17:25:28	LINE START - SS04-007-017 shot 1001 time 1-19-2005 17:24:32.624806
1007	19/01/2005 17:25:29	SOL String pressures 1:1994.2 PSI 2:1959.2 PSI 3:1955.7 PSI
	19/01/2005 17:25:29	Volume source 1 3040 cu in (ideal volume 3040)
	19/01/2005 17:25:29	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	19/01/2005 17:25:29	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	19/01/2005 17:25:29	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1007, 8730, '1-19-2005 17:25:27.584800')
	19/01/2005 17:25:30	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	19/01/2005 17:25:30	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	19/01/2005 17:25:30	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1007, 8730, '1-19-2005 17:25:27.584800')
	19/01/2005 17:25:30	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	19/01/2005 17:25:30	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	19/01/2005 17:25:30	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1007, 8730, '1-19-2005 17:25:27.584800')
	19/01/2005 17:25:31	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	19/01/2005 17:25:31	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	19/01/2005 17:25:31	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1007, 8730, '1-19-2005 17:25:27.584800')
	19/01/2005 17:25:31	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	19/01/2005 17:25:31	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	19/01/2005 17:25:31	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1007, 8730, '1-19-2005 17:25:27.584800')
	19/01/2005 17:25:31	stats - updateShotpoint: Duplicate shotpoint or stats slow, one shotpoint dropped
	19/01/2005 17:25:31	stats - fireSQL: ... ERROR: Cannot insert a duplicate key into unique index shotpoint_key
	19/01/2005 17:25:31	stats - fireSQL: insert into shotpoint (number, line_id, stime)values(1007, 8730, '1-19-2005 17:25:27.584800')
1012	19/01/2005 17:26:13	String_2 Cluster_2 Gun_4 (300 cu in) fired 1.8 mS late.
1013	19/01/2005 17:26:22	String_2 Cluster_2 Gun_4 (300 cu in) fired 1.2 mS late.
1027	19/01/2005 17:28:30	String_2 Cluster_2 Gun_4 (300 cu in) fired 1.5 mS late.
1028	19/01/2005 17:28:39	String_2 Cluster_2 Gun_4 (300 cu in) fired 1.3 mS late.
1031	19/01/2005 17:29:05	Operator command, GUN String_2 Cluster_2 Gun_4 Disable
	19/01/2005 17:29:05	Operator command, GUN String_2 Cluster_2 Gun_3 Disable
	19/01/2005 17:29:07	Operator command, GUN String_2 Cluster_1 Gun_1 Enable
	19/01/2005 17:29:07	Operator command, GUN String_2 Cluster_1 Gun_2 Enable

Line Log: SS04-007-017 (continued)

Shotpoint	Log Time	Message
1032	19/01/2005 17:29:15	Spread error 6.0mS (limit 2.0mS) earliest String_3 Cluster_2 Gun_3 (error -0.3mS) latest String_2 Cluster_1 Gun_1 (error 5.7mS)
	19/01/2005 17:29:15	String_2 Cluster_1 Gun_2 (300 cu in) fired 4.6 mS late.
	19/01/2005 17:29:15	String_2 Cluster_1 Gun_1 (300 cu in) fired 5.7 mS late.
1033	19/01/2005 17:29:24	Spread error 6.0mS (limit 2.0mS) earliest String_2 Cluster_1 Gun_1 (error -5.8mS) latest String_3 Cluster_1 Gun_1 (error 0.2mS)
	19/01/2005 17:29:24	String_2 Cluster_1 Gun_2 (300 cu in) fired 4.5 mS early.
	19/01/2005 17:29:24	String_2 Cluster_1 Gun_1 (300 cu in) fired 5.8 mS early.
1062	19/01/2005 17:33:47	String_1 Cluster_1 Gun_2 (250 cu in) fired 1.1 mS late.
2171	19/01/2005 20:23:04	String_1 Cluster_1 Gun_2 (250 cu in) fired 1.1 mS late.
2246	19/01/2005 20:34:52	String_1 Cluster_1 Gun_2 (250 cu in) fired 1.4 mS late.
	19/01/2005 20:52:05	Missed Shot(s). Last S.P. 2352 this shot 0 (expected increment/decrement 1)
	19/01/2005 20:52:08	LOST SHOT - TCU did not detect T0 - Failed to see fire signal before timeout (predict settings wrong ?)
	19/01/2005 20:52:14	END OF LINE SS04-007-017 shot 0 time 1-19-2005 20:52:8.375000
	19/01/2005 20:52:14	EOL String pressures 1:2046.0 PSI 2:2004.3 PSI 3:2004.0 PSI
	19/01/2005 20:52:14	EOL Volume source 1 3040 cu in.
	19/01/2005 20:52:39	Timeout on message read from Navigation system
	19/01/2005 20:53:01	Operator Command SHOT DISABLE
		Totalshots on line = 1347 Shots with one or more errors 10 (0.7%)
		Shots with bad timing 10 (0.7%)