

TIN DISTRIBUTION OF FRACTION

0 10 20 30 40 50 60 70 80 90 100

TIN DISTRIBUTION-TOTAL

0	
10	1180
20	
30	850
40	800
50	
60	425
70	300
80	212
90	150
100	106
	75
	-75 NOT TESTED

2.95

2.96

WEIGHT DISTRIBUTION OF FRACTION

0 10 20 30 40 50 60 70 80 90 100

WEIGHT DISTRIBUTION-TOTAL

0	
10	1180
20	
30	850
40	600
50	
60	425
70	300
80	212
90	150
100	105
	75
	-75 NOT TESTED

660