

TABLE 4.2

Drillhole Summary, Hummocky Hills Programme

Drillhole No.	Easting mE	Northing mN	Collar RL m	Overburden Thickness m	Triassic Thickness m	Dolerite Thickness m	Total Depth m
R0130	519100	5374400	170	-	14.5	51.1+	75.6
R0131	521030	5375580	200	0.7	2.3	57.0+	60.0
R0132	533610	5376100	190	3.5	6.8	9.2+	19.5
R0133	522300	5374380	170	1.1	34.7	9.2+	45.0