KG04 BH14-1009

0374_1412

LEGEND:

| | | | |
|---|---|---|---|
| v | Upper metavolcanics | bh/gh ch/gh | Banded footwall beds |
| | | bph | Biotite pyroxene hornfels |
| bh/ph | Banded hornfels | lv | Lower metavolcanics |
| ch | Marble | q | Quartzite |
| bh | Biotite hornfels | | |
| pgh | Pyroxene garnet hornfels | ap | Aplite |
| gh | Garnet hornfels | gr | Granite |

strike and dip
strike and dip vertical
joint
joint vertical
unconformity
relative movement
rise extending through level
head of rise
foot of rise
survey station

geological boundary
minor fault
major fault

b back
f floor
r road
s spad

0374_1412

5 cm

DATE:
DRAWN: M.vdS.
GEOLOGY: R.E.S-D
CHECKED:

KING ISLAND SCHEELITE

SCALE 1:500

No. KG04 BH14-1009

BOLD HEAD MINE

MAIN DECLINE

27 JUN 1981