



SCALE 1:500

Notes:  
 Poor ground conditions along intersection of faults F<sup>1</sup> and F<sup>2</sup>, F<sub>6</sub> and F<sub>3</sub>  
 Collapsed area along W46 drive  
 Very poor ground (blocky) along W48 drive.



LOCATION  
 DOLPHIN MINE

SUBJECT  
 LOWER WEDGE - Lrrr 1  
 - 215m LEVEL

**KIS** KING ISLAND SCHEELITE  
 A DIVISION OF WARMAN INTERNATIONAL

GRASSY KING ISLAND

PLAN NUMBER

5 cm  
 0374-1710