



BOLD HEAD MINE VEHICLES

UNIT NO.	MAKE AND MODEL	VENT REQD
17-6	CAT. 980B	12.9m ³ /sec
17-9	CAT 950	6.2m ³ /sec
12-1	KIRUNA	14.0m ³ /sec
12-3	KIRUNA	14.0m ³ /sec
18-4	A/C JUMBO	3.7m ³ /sec
18-6	TAMROCK JUMBO	3.7m ³ /sec
16-4	A/C GRADER	3.7m ³ /sec
6-2	INTER. TRUCK	8.6m ³ /sec
2-10	L/ROVER	2.2m ³ /sec
2-11	L/ROVER	2.2m ³ /sec
L-9	L/ROVER(Geopetko)	2.2m ³ /sec
13-1	FIAT TRACT.	1.4m ³ /sec

N. 52
 FORCING 6.0 m³/sec
 EXHAUST 4.5 m³/sec

DECLINE EXHAUST DUCT
 V. 185
 187
 188
 197
 199
 201
 NEEDS TAPING

N. 52
 EXHAUST DUCT DISJOINTED
 AT V. 208 - 218

EXHAUST FANS			FORCING FANS		
No	HP	LOCATION	No	HP	LOCATION
1E	60	PORTAL	1F	25	L43 DRIVE
2E	60	MAIN DECLINE	2F	40	M52 DRIVE
3E	60	N52 DRIVE	3F	40	N52 DRIVE
4E	60	MAIN DECLINE	4F	25	N62/P62
5E	60	SURFACE	5F	10	MAIN DECLINE
6E	60	SURFACE			

TEST NO.	GAS TEST										ANEMOMETER		DUST CM/3
	20% O ₂	50 CO	5000 CO ₂	25 NO _x	5 HCHO	5 NO ₂	5 SO ₂	10 H ₂ S	FORCING	EXHAUST			
NO.1	NT	NIL	200	NIL	NIL	NIL	NIL	NIL	NIL	NIL	NB	NB	NIL
NO.2	NT	NIL	200	NIL	NIL	NIL	NIL	NIL	NIL	NIL	6.1 m ³ /sec	NB	NIL
NO.3	NT	NIL	200	NIL	NIL	NIL	NIL	NIL	NIL	NIL	5.7 m ³ /sec	11.6 m ³ /sec	57
NO.4	NT	10	1200	10	NIL	NIL	NIL	NIL	NIL	NIL	4.5 m ³ /sec	NB	30
NO.5	NT	5	200	10	NIL	1	NIL	NIL	NIL	NB	NB	NB	130
NO.6	NT	5	500	5	NIL	1	NIL	NIL	NIL	NB	NB	NB	NIL
NO.7	NT	NIL	100	NIL	NIL	NIL	NIL	NIL	NIL	NB	NB	NB	NIL
NO.8	NT	Trace	200	Trace	NIL	NIL	NIL	NIL	NIL	NB	2.0 m ³ /sec	NB	NIL
NO.9	NT	NIL	200	Trace	NIL	NIL	NIL	NIL	NIL	NB	NB	NB	70
NO.10													

21 - 8 - 75

22/06/75

KING ISLAND SCHEELITE LTD.
 No 1-5-100
BOLD HEAD MINE
 VENTILATION TEST PLAN

DATE 7-2-75
 SURVEYED J.C.
 DRAWN J.C.
 TRACED R.B.
 CHECKED G.M.