


5 cm

0374_2982

65

Dec.



H15

H15

N15

Dec.

Decline

armco + inspection tower

RIB PILLAR

CENTRAL FAULT

75 Level

-75m RL

-100m RL

-150m RL

RS 16

12

14

16

18

20

22

24

26

28

g_h

g_h

p_{g_h}

a_{tmu3}