



NUMBERS # 12, ~~6~~, 10

INSTALLATION DETAILS:

LOCATION LOWER PIT
 LIFT 2ND
 R.L. -220.2
 DATE 25.6.1980

CALIBRATION

1 Volt = 1°
 Linear over the range 0 - 0.4V

INCLINOMETER RESULTS

DATE	# 12			# 6			# 10		
	Reading	Δ Angle	Inclination	Reading	Δ Angle	Inclination	Reading	Δ Angle	Inclination
16.7.80 ^{14:00}	0			0.254	0.319 (9)		0.333	0.405	
16.7.80 ^{17:00}				0.383					0.477
17.7.80				+0.408	0.405 (10)		+0.476	0.478	
17.7.80				+0.409					+0.478
17.7.80 ^{16:00}				+0.398			+0.481		
18.7.80				+0.408			+0.485		
21.7.80				+0.935			+0.482		
22.7.80				+0.935			+0.502		
23.7.80				+0.933			+0.506		
24.7.80				+0.936			+0.510		
25.7.80				+0.939			+0.524		
28.7.80				+0.934			+0.518		
29.7.80				+0.936			+0.525		
30.7.80				+0.936			+0.520		
31.7.80				+0.936			+0.522		
1.8.80				+0.922			+0.523		
4.8.80				+0.927			+0.517		
5.8.80				+0.926			+0.516		
6.8.80				+0.926			+0.516		
7.8.80				+0.926			+0.513		
8.8.80				+0.926			+0.514		
11.8.80				+0.888			+0.505		
12.8.80				+0.912			+0.508		
13.8.80				+0.910			+0.509		
14.8.80				+0.908			+0.509		
15.8.80				+0.767			+0.510		
18.8.80				+0.828			+0.509		
19.8.80				+0.826			0.505		
20.8.80				+0.824			0.518		
21.8.80				+0.805			0.505		
22.8.80				+0.833			0.504		
25.8.80				+0.832			0.505		
26.8.80				+0.830			0.505		
27.8.80				+0.833			0.504		
28.8.80				+0.834			0.500		
29.8.80				+0.839			0.500		
1.9.80				+0.839			0.498		
3.9.80				+0.841			0.491		
7.9.80				+0.837	(11)		0.493		

NOT CONNECTED

entered correctly as 0.9336