

NUMBERS

~~15, 14, 13~~ 15, 14, 13

INSTALLATION DETAILS:

LOCATION LOWER PIT
 LIFT 2ND
 R.L. -220.2
 DATE 25.6.1980

CALIBRATION

1 volt = 1°
 Linear over the
 range 0 - 0.4 volt.

INCLINOMETER
RESULTS

DATE	15			14			13		
	Reading	Δ Angle	Inclination	Reading	Δ Angle	Inclination	Reading	Δ Angle	Inclination
16.7.80 ^{17.00}	-0.343	-0.374		-0.076	-0.098 (9)		+0.046	0.418	
16.7.80 ^{17.00}	-0.404			-0.119			+0.790		
17.7.80	-0.404			-0.130	-0.131 (10)		+0.709	0.497	
17.7.80	-0.404		-0.131			+0.716			
17.7.80 ^{16.00}	-0.404		-0.131			+0.067			
18.7.80	-0.405		-0.133			+0.0796			
21.7.80	-0.406		-0.266			-0.447			
22.7.80	-0.406		-0.255			-0.447			
23.7.80	-0.406		-0.256			-0.447			
24.7.80	-0.406		-0.256			-0.447			
25.7.80	-0.407		-0.266			-0.448			
28.7.80	-0.406		-0.262			-0.448			
29.7.80	-0.407		-0.269			-0.448			
30.7.80	-0.407		-0.204			-0.448			
31.7.80	-0.407		-0.263			-0.448			
1.8.80	-0.407		-0.237			-0.448			
4.8.80	-0.407		-0.258			-0.448			
5.8.80	-0.407		-0.261			-0.448			
6.8.80	-0.407		-0.260			-0.448			
7.8.80	-0.410		-0.256			-0.448			
8.8.80	-0.411		-0.265			-0.448			
11.8.80	-0.410		-0.255			-0.447			
12.8.80	-0.410		-0.256			-0.448			
13.8.80	-0.411		-0.195			-0.448			
14.8.80	-0.410		-0.260			-0.448			
15.8.80	-0.410		-0.262			-0.447			
18.8.80	-0.410		-0.192			-0.447			
19.8.80	-0.410		-0.200			-0.447			
20.8.80	-0.410		-0.285			-0.447			
21.8.80	-0.410		-0.258			-0.448			
22.8.80	-0.410		-0.260			-0.447			
23.8.80	-0.410		-0.252			-0.447			
26.8.80	-0.410		-0.264			-0.447			
27.8.80	-0.411		-0.266			-0.447			
28.8.80	-0.411		-0.263			-0.447			
29.8.80	-0.411		-0.248			-0.447			
7.9.80	-0.411		-0.198			-0.448			
3.9.80	-0.410		-0.139			-0.447			
4.9.80	-0.411		-0.135	(4)		-0.448			