

W
V
U
40 450 E
T
S
R
Q
P
40 400 E
O
N
M
L
K
40 350 E
J
I
H
G
F
40 300 E
E
D
C
B
A
40 250 E

MAIN DECLINE

V 53

N 54

N 53

O 49

N 53

O 42

Part B lens
fault block
(B lens East)



MICROFILMED

0374_803

| | | |
|----------|------------------------------|-------------------------|
| | KING ISLAND SCHEELITE | |
| | A1 | SCALE 1:500 O4BH14-1008 |
| DATE | BOLD HEAD MINE | |
| SURVEYED | B LENS FAULT BLOCK & PART | |
| DRAWN | B LENS EAST | |
| TRACED | xxxyb | |
| CHECKED | | |

74 73 72 71 70 10 700 N 69 68 67 66 65 10 650 N 64 63 62 61 60 10 600 N 59 58 57 56 55 10 550 N 54 53 52 51 50 10 500 N 49 48 47 46 45 10 450 N 44 43 42 10 400 N

MAIN DECLINE 300 - 1000