



Map 1 - 1872 Glenorchy Debris Flow - Property Locations, Watercourses and Recorded Damage at Glenorchy

M.D. Stevenson and R.N. Woolley, 2016

To accompany: Historical assessment of the 1872 Glenorchy debris flow: a basis for modelling the large debris flow hazard from the Wellington Range, Hobart
Tasmanian Geological Survey report 2016/02



- | | |
|------------------------|---|
| 1872 Features | Damage Severity to 1872 Structures |
| Flood wall (1858) | Catastrophic |
| Flood wall (post-1872) | Major |
| Stone wall | Medium |
| Water-race | Minor |
| Property boundary | Not damaged |
| Pond | Damage severity unknown |
| | Other Features |
| | Watercourse |
| | 5m contour (LIDAR derived, 2011 topography) |

Aerial photography acquired February 2011.

5m contours derived from Mount Wellington LIDAR dataset (2011), available from the LIST. (Note: may include minor interpolation anomalies.)

Map produced by Spatial Information Services, Mineral Resources Tasmania.

Website: www.mrt.tas.gov.au



While every care has been taken in the preparation of this data, no warranty is given as to the correctness of the information and no liability is accepted for any statement or opinion or for any error or omission. No reader should act or fail to act on the basis of any material contained herein. Readers should consult professional advisers. As a result the Crown in Right of the State of Tasmania and its employees, contractors and agents expressly disclaim all and any liability including all liability from or attributable to any negligent or wrongful act or omission to any persons whatsoever in respect of anything done or omitted to be done by any such person in reliance whether in whole or in part upon any of the material in this data.

© Crown copyright reserved.

