




Map 2 - 1872 Glenorchy Debris Flow - Runout Interpretation based on Recorded Damage and Historical Reconstruction

M.D. Stevenson, 2016

To accompany: 'Historical assessment of the 1872 Glenorchy debris flow: a basis for modelling the large debris flow hazard from the Wellington Range, Hobart' Tasmanian Geological Survey report 2016/02



- | | |
|------------------------|---|
| 1872 Features | 1872 Debris Flow Interpretation |
| Flood wall (1858) | Coarse debris |
| Flood wall (post-1872) | Mud (limited extent information) |
| Stone wall | Other Features |
| Water-race | Watercourse |
| Property boundary | 5m contour (LIDAR derived, 2011 topography) |
| Pond | |

Aerial photography acquired February 2011.

5m contours derived from Mount Wellington LIDAR dataset (2011), available from the LIST. (Note: may include minor interpolation anomalies.)

Map produced by Spatial Information Services, Mineral Resources Tasmania.

Website: www.mrt.tas.gov.au

While every care has been taken in the preparation of this data, no warranty is given as to the correctness of the information and no liability is accepted for any statement or opinion or for any error or omission. No reader should act or fail to act on the basis of any material contained herein. Readers should consult professional advisers. As a result of the Crown in Right of the State of Tasmania and its employees, contractors and agents expressly disclaim all and any liability including all liability from or attributable to any negligent or wrongful act or omission to any persons whatsoever in respect of anything done or omitted to be done by any such person in reliance whether in whole or in part upon any of the material in this data.

Crown copyright reserved.

