



(b)

## APPENDIX 'B'

## ADS-203 CALIBRATION REPORT

OFF LAKES ENTRANCE - 30 AUGUST 1967

A

B

A and B - previously surveyed points.

P - Hi-Fix antenna on calibration boat.

P

ATM Co-ordinates

A (589 062.1 East  
(326 763.0 NorthB (594 417.0 East  
(328 295.3 North

Fix	G 1	G 3	H I
Time	0942	0952	0957
/A	77° 03' 08"	71° 36' 01"	61° 39' 20"
/B	34° 12' 26"	37° 10' 34"	49° 00' 59"
Computed Patt. I	009.21	010.50	017.61
Observed Patt. I	009.12	010.42	017.54
Monitor Correction	.00	.00	.00
True Observed Patt. I	009.12	010.42	017.54
(C - O) Correction	+ 0.09	+ 0.08	+ 0.07
Computed Patt. II	035.58	032.82	029.08
Observed Patt. II	035.10	032.30	028.59
Monitor Correction	.00	.00	.00
True Observed Patt. II	035.10	032.30	028.59
(C - O) Correction	+ 0.48	+ 0.52	+ 0.49