



SECTION V
CONCLUSION

No geologic interpretation was done by the field crew.
A ship position, water depth field map was prepared onboard for all areas.

The overall misfire rate was 3.6 percent. No more than two consecutive shots were misfires and less than 3 percent of the shots were misfires in any 5 mi length of line.

Average streamer depth was 45 ft. Ambient noise levels were checked daily.

Signal level was determined by straight-gain recordings and signal-to-noise ratios determined. Signal-to-noise ratio was never less than 40/1 at 1.0 sec which was obtained with 50 lb charges and shallow basement reflector.

Respectfully submitted,

D. S. Cameron

Q. C. Seismologist