

DOM.

288032 P8/2

Cormoran 1 Daily Report 2/7/20.

Bottom footage 8663. Progress 35'

currently running well slot for velocity survey.

Geology

8620 - 8650 10-30% Volcanics
60% Slab
10% Sandstone, tan
fine to very fine spotty fluorescence
no cut.

8650 - 8663. 40% volcanics
50% Slab
10% Sandstone.

Gas readings

8620' - 8650'

cuttings 10
Hot Wire 12-20
C1 500-800
C2 40-90.

8650 - 8663.

cuttings 10
Hot wire 18
C1 800
C2 70.

Ran IES & GRD logs 8658 - 2953.

FIT NO1, - 6889

Recovered 0.6 cubic feet gas
& 230 cc mud

Shut in pressure 100 psi

Volcanic interval from logs - 8018 - 8268
determined from electric logs.

Will run more FITs before resuming drilling.

J. M.