

5 cm

338075



EXPLORATION LOGGING OF AUSTRALIA, INC.

A Geological-Engineering Service

PERTH ADDRESS 69 GREAT EASTERN HIGHWAY VICTORIA PARK WESTERN AUSTRALIA
PHONE 61 4437 CABLE EXLOGG PERTH

CORE ANALYSIS REPORT

COMPANY ESSO-BHP
WELL CORMORANT #1
LOCATION/FIELD OFFSHORE/BASS BASIN
COUNTY STATE TASMANIA
COUNTRY AUSTRALIA

DATE 7 JULY 1970
DEPTH 9098 TO 9128
GEO-ENGINEER CRAIG; WEARE
CORE No. 13

REMARKS CUT 30FT; RECOVERED 29FT: SANDSTONE, LIGHT
GREY, VERY FINE TO FINE, HARD, SILTY; LAMINATED
WITH DARK GREY, SILTY SHALE; SANDSTONE HAS BRIGHT
YELLOW, SPOTTY FLUOR; GIVES LIGHT YELLOW CUT
UPON CRUSHING.

.... SAND
--- SILTY SAND
--- SILTST.
--- SHALE
□□□□ LIME
□□□□ CONGL.
□
□

TABULAR DATA

ANALYSIS GRAPH

