

Don 

362054

98/2

30th October

Daily Report

Barrow 1

Present depth 5081'

Drilled out of sand at 4120'.
From 3480' greenish sediments in
place & tentatively correlated with
Cretaceous from Sublake section.

4120 -	4210 -	mantlestone
4210 -	4330 -	Sand
4330 -	4510 -	interbedded sand & mud
4510 -	5040	mantlestone

Gas Readings

Section	4950 - 4960	-	9000 cc
			500 cc
			100 cc
			100 cc
			5000 <u>CO₂</u>

Accident position bit stuck at 4400'
while pulling out. Not
thought to be serious & expect
to resume drilling during day.

[Signature]

[Signature]