

COMPANY	ESSO AUSTRALIA LTD.	Enclosure 15
WELL	DONDU 1	SCHL. FR. 9600
FIELD	WILDCAT	SCHL. TD. 9607
COUNTRY	AUSTRALIA	DRLR. TD. 9603
STATE	TASMANIA	Elev. KB 32
		DF 37
		GI -269

DETAILLOG 369063

5"=100'

INTERVAL TRANSIT TIME
MICROSECONDS PER FOOT

T³R²Z²

5" 140 90 40



5" T³R²Z²

INTERVAL TRANSIT TIME
MICROSECONDS PER FOOT

COMPANY ESSO AUSTRALIA LTD. SCHL. FR. 9600
WELL DONDU 1 SCHL. TD. 9607
FIELD WILDCAT DRLR. TD. 9603
COUNTY AUSTRALIA STATE TASMANIA Elev. KB 32
DF 37
GI -269

CALIBRATION DATA

DOWN HOLE CALIBRATION AFTER SURVEY

140,5sec
100,5sec
80,5sec
60,5sec
40,5sec
Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

140,5sec
100,5sec
80,5sec
60,5sec
40,5sec
Mechanical Zero

REPEAT SECTION

CALIBRATION DATA

COMPANY ESSO AUSTRALIA LTD. SCHL. FR. 9600
WELL DONDU 1 SCHL. TD. 9607
FIELD WILDCAT DRLR. TD. 9603
COUNTY AUSTRALIA STATE TASMANIA Elev. KB 32
DF 37
GI -269