243135

SCHLUMBERGER

# DIPMETER LOG INTERPRETATION

COMPANY ESSO AUSTRALIA LTD.
BASIN OFFSHORE
FIELD GIPPSLAND
WELL TARRAGON #1
STATE TASMANIA
COUNTRY AUSTRALIA

| | |
|---|---|
| Dipmeter Recorded | 1 |
| Dipmeter Processed | 1 |
| Dipmeter Interpreted | 1 |
| Prints | 1 |
| Sepias | 1 |
| Film | 1 |

CM-340

RUN DATA

| | BIT | CSG | DATA |
|---|---|---|---|
| No. | 4 | 3 | |
| Diameter | 8.5" | 13.375" | |
| Log Measure | DP | DP | |
| Driller's Depth | 10282' | 3000' | |
| Logger's Depth | 10287' | 3000' | |
| Bottom Driller | 10282' | | |
| Bottom Logged | 10287' | | |
| Depth Reached | 10282' | | |
| Casing Driller | 3000' | | |
| Casing Logger | 3000' | | |
| Recorded By | R.WATKINS | | |

INTERPRETATION DATA

| | |
|---|---|
| Top Processed Interval | 3100' |
| Bottom Processed Interval | 10282' |
| Interval Processed | 7182' |
| Date Processed | 31.10.73 |
| Computer Program Used | CYBERDIP |
| Computer | CDC 1700 |
| Computer Center | MELBOURNE |
| Operator | JOHNSTONE |

REMARKS: THIS LOG IS PRESENTED AS A PRELIMINARY INTERPRETATION. IT IS SUBJECT TO REVISION AS MORE DATA BECOME AVAILABLE. THE ACCURACY OF THE INTERPRETATION IS DEPENDENT ON THE ACCURACY OF THE DIPMETER AND OTHER LOGS USED AND ON THE INTERPRETER'S INTERPRETATION OF THE DATA.

HOLE DEVIATION & DIRECTION

Degrees: 0 1 2 3 4 5 6

DEPTH

DIP ANGLE AND DIRECTION

Bedding
Fracture
Fault

0 10 20 30 40 50 60 70 80

1 cm

"MAGNETIC DECLINATION 20 EAST OF NORTH"
5 DEGREES

CORRELATION INTERVAL SCALE CONVERSION
1" = 100'
1 cm = 1 m



SCHLUMBERGER WELL SURVEYING CORP. HOUSTON, TEXAS
SCHLUMBERGER OVERSEAS, S.A. PARIS, FRANCE