

343126 OR-340

ENCLOSURE B9
Schlumberger

ISF

COUNTY	AUSTRALIA	COMPANY	ESSO AUSTRALIA LTD.
FIELD or LOCATION	WILDCAT	WELL	NARIMBA 1
WELL	NARIMBA 1	FIELD	WILDCAT
COUNTY	AUSTRALIA	STATE	TASMANIA
LOCATION	LAT: 40° 16' 16.153" S LONG: 145° 43' 53.327" E	Other Services:	SLK, HDT, FDC/CNL/GR ST
Permanent Datum:	MSL	Elev.:	0
Log Measured From:	KB	F. Above Perm. Datum	
Drilling Measured From:	KB	Elev.:	KB 32 DF 31 GL -253
Date	1 OCT 73	Run No.	FIVE 2"
Depth-Driller	11003	Depth-Logger	10992
Btm. Log Interval	10986	Top Log Interval	10250
Casing-Driller	9578 @ 8808	Casing-Logger	8789
Bit Size	8 1/2	Type Fluid in Hole	LIGNOSULFONATE
Dens.	11.0	Visc.	44
pH	9.8	Fluid Loss	4.4 ml
Source of Sample	FLOWLINE	Rm @ Meas. Temp.	0.80 @ 69 °F
Rmf @ Meas. Temp.	0.56 @ 68 °F	Rmc @ Meas. Temp.	1.17 @ 68 °F
Source: Rmf	FLOWLINE	Rmc	0.21 @ 264 °F
Rm @ BHT	0.21 @ 264 °F	Time Since Circ.	7 1/2 HRS
Max. Rec. Temp.	264/265 °F	Equip. Location	2080 SAL
Recorded By	CHAFFE/CLARKE	Witnessed By	SVALBE

FOLD HERE The well name, location and borehole reference data were furnished by the customer.

Date	1 OCT 73	Run No.	FIVE
Depth-Driller	11003	Depth-Logger	10993
Btm. Log Interval	10986	Top Log Interval	10250
Casing-Driller	9578 @ 8808	Casing-Logger	8789
Bit Size	8 1/2	Type Fluid in Hole	LIGNOSULFONATE
Dens.	11.0	Visc.	44
pH	9.8	Fluid Loss	4.4 ml
Source of Sample	FLOWLINE	Rm @ Meas. Temp.	0.80 @ 69 °F
Rmf @ Meas. Temp.	0.56 @ 68 °F	Rmc @ Meas. Temp.	1.17 @ 68 °F
Source: Rmf	FLOWLINE	Rmc	0.21 @ 264 °F
Rm @ BHT	0.21 @ 264 °F	Time Since Circ.	7 1/2 HRS
Max. Rec. Temp.	264/265 °F	Equip. Location	2080 SAL
Recorded By	CHAFFE/CLARKE	Witnessed By	SVALBE

Changes in Mud Type or Additional Samples		Scale Changes	
Date	Sample No.	Type Log	Depth
Depth-Driller		Scale Up Hole	Scale Down Hole
Type Fluid in Hole			
Dens.	Visc.		
pH	Fluid Loss		
Source of Sample			
Rm @ Meas. Temp.			
Rmf @ Meas. Temp.			
Rmc @ Meas. Temp.			
Source: Rmf			
Rm @ BHT			
Rm @ BHT			
Rm @ BHT			

Run No.	5	REMARKS:
Ind. Panel No.	A-136	
Mem. Panel No.	UA-53	
Ind. Cart. No.	MA-123	
Ind. Sonde No.	S-124	
Sonic Panel No.		
Oscil. Panel No.		
Sonic Cart. No.		
Sonic Sonde No.		
G.R. Cart. No.		
G.R. Panel No.		
Caliper No.		
TTR No.		
S.E.	6.4	Service Order No.-
SBR	1	API Serial No.-
Cent. Device		Check one, filling in blanks where applicable:
Stand off-Inches	1 1/2"	<input type="checkbox"/> Surface determined sonde errors used for 6FF40.
Time Const.-Sec.		<input type="checkbox"/> 6FF40 sonde error corrected for
Speed-F.P.M.		borehole signal at Rm
		<input type="checkbox"/> 6FF40 zero set in hole at depth of
		feet.



COMPANY	ESSO AUSTRALIA LTD	SCHL. FR.	10986
WELL	NARIMBA 1	SCHL. TD.	10993
FIELD	WILDCAT	DRIL. TD.	11003
COUNTY	AUSTRALIA	STATE	TASMANIA
		Elev.	KB 32 DF 31 GL -253

5 cm