

MASTER CALIBRATION
 IRIS-5-P
 ILS-R-5-3
 IRG-D-7A
 IRS-D-7S
 JUNE 1972

Mechanical Zero

SONIC ERROR (T-11 NORMAL)

Z-R-M

500 FT/M

100

1

ZERO SIGNAL IN AIR (4.2 MPa)

MECHANICAL ZERO

DOWN HOLE CALIBRATION AFTER SURVEY

140 μSec

100 μSec

80 μSec

60 μSec

40 μSec

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

140 μSec

100 μSec


80 μSec

60 μSec

40 μSec

Mechanical Zero

REPEAT SECTION



CALIBRATION DATA

5 cm

COMPANY ESSO AUSTRALIA LTD.
 WELL POON BOON
 FIELD WILDCAT
 COUNTY AUSTRALIA STATE TASMANIA

SCHL. FR. 8806
 SCHL. TD. 8813
 DRIL. TD. 8827
 Elev. KB 32
 DF 31
 GI 259