






	16" NORMAL		INDUCTION	
	0	4	500	0
	0	20		
	0	200		
	INDUCTION			
	0	20		
	0	200		
	0	200		
SPONTANEOUS POTENTIAL 100 millivolts	DEPTHS	RESISTIVITY ohms - m ² /m	CONDUCTIVITY millimhos - m ² /m $\frac{1000}{\text{ohms} \cdot \text{m}^2/\text{m}}$	

COMPANY	ESSO AUSTRALIA	SCHL. F.R.	10477
WELL	PRAWN A-1	SCHL. T.D.	10478
FIELD	WILDCAT	DRLR. T.D.	10477
COUNTRY	AUSTRALIA	STATE	TASMANIA

CALIBRATION FILMS



DOWN HOLE CALIBRATION AFTER SURVEY	Diode Error	
	Sonde Error	
	ZERO	
	Calibrate Signal	
DOWN HOLE CALIBRATION BEFORE SURVEY	Diode Error	
	Sonde Error	
	ZERO	
	Calibrate Signal	

SURFACE CALIBRATION 24 JAN 1968 IRP-C 721 IRC-C 711 IRS-M 581 ITL-C 721 IAP-D 807	Test Loop Signal	
	Electrical Zero	
	Diode Error	
	Sonde Error	
	Calibrate Signal	
	Electrical Zero	
	Mechanical Zero	
	Calibrate Signal	

