


140 90 40
190 140

INTERVAL TRANSIT TIME
MICROSECONDS PER FOOT


CALIBRATION DATA

COMPANY ESSO AUSTRALIA LTD.
 WELL TOOLKA No. 1 A
 FIELD WILDCAT
 COUNTY AUSTRALIA STATE TASMANIA


SCHL. FR 8894'
 SCHL. TD 8900'
 DRLR TD 8907'
 Elev: KB 32'
 DF 31'
 GI -258'




INTEGRATOR CHECK



DOWN HOLE CALIBRATION AFTER SURVEY



DOWN HOLE CALIBRATION BEFORE SURVEY



CALIBRATION DATA

COMPANY ESSO AUSTRALIA LTD.
 WELL TOOLKA No. 2. A
 FIELD WILDCAT
 COUNTY AUSTRALIA STATE TASMANIA

SCHL. FR 8894'
 SCHL. TD 8900'
 DRLR TD 8907'
 Elev: KB 32'
 DF 31'
 GI -258'

← 5 cm →