

3.6 Abandonment:

The well was abandoned in accordance with the Tasmanian Department of Mines regulations. Cement plugs were set between 1201 to 1271m and 251 to 146m (Figure 2). The abandonment report letter follows: