

446236

SEQUENCE OF OPERATIONS



OEC-872-1-B-SIN

TEST NUMBER	RIG NAME	PAGE	OF
-------------	----------	------	----

DST#1-6

DIAMOND M. EPOCH

3 14

CUSTOMER	WELL NAME OR NUMBER	FIELD	RIG AREA
----------	---------------------	-------	----------

AMOCO AUSTRALIA PETROLEUM CO.

PELICAN #5

PELICAN

BASS STRAIT

CUSTOMER REPRESENTED BY	OTIS TEST SUPERVISOR
-------------------------	----------------------

Mr. J Guillery/E Bowden/J Harkin/T Mosness

TONY WOOLHAM / GRAHAM MCKAY

DATE	TIME	OPERATIONS	
			1
13MAR86	0130	LAI D BACK SUBSEA LUBRICATOR VALVE IN DERRICK	2
		GENERAL MAINTENANCE OF PRODUCTION TESTING EQUIPMENT	3
		PICKED UP SUBSEA TEST TREE AND RAN IN HOLE	4
		PICKED UP SUBSEA LUBRICATOR VALVE AND RAN IN HOLE	5
	2130	PICKED UP SURFACE TEST TREE AND MADE UP TO LANDING STRING	6
	2250	SET R.T.T.S. PACKER	7
	2320	PRESSURE TESTED KILL VALVE / MASTER VALVE AND SAFETY VALVE ON	8
		SURFACE TEST TREE TO 8000 PSI - OKAY	9
	2345	PRESSURE TESTED TUBING AGAINST CHOKE MANIFOLD VALVE TO 8000 PSI - OKAY	10
		RIGGED UP COFLEXIP HOSE AND CHOKE MANIFOLD	11
		FLUSHED LINES	12
14MAR86	0935	PRESSURE TESTED HEATER INLET AND BYPASS VALVES TO 5000 PSI - OKAY	13
	0950	PRESSURE TESTED CHOKE TO 8000 PSI - OKAY	14
	1300	PERFORATING GUNS RAN IN THE HOLE	15
	1445	TEST ZONE PERFORATED (SEE FIELD READINGS)	16
16MAR86	2230	REVERSED OUT TEST STRING ENDING DST #2	17
	2320	BROKE OUT SURFACE TEST TREE AND LAID DOWN	18
17MAR86	0015	BROKE OUT SUBSEA LUBRICATOR VALVE AND LAID BACK IN DERRICK	19
	0040	SERVICE BROKE SUBSEA TEST TREE FOR INSPECTION	19