

446246

SEQUENCE OF OPERATIONS

OEC-872-1-B-SIN

TEST NUMBER

RIG NAME

PAGE

OF

DST#1-6

DIAMOND M. EPOCH

13

14

CUSTOMER

WELL NAME OR NUMBER

FIELD

AREA

AMOCO AUSTRALIA PETROLEUM 'CO.

PELICAN #5

PELICAN

BASS STRAIT

CUSTOMER REPRESENTED BY

OTIS TEST SUPERVISOR

Mr. J Guillery/E Bowden/J Harkin/T Mosness

TONY WOOLHAM / GRAHAM MCKAY

DATE

TIME

OPERATIONS

DATE	TIME	OPERATIONS	
09APR86	1330	UNSEATED PACKER AND CONTINUED CIRCULATION	1
	1615	PULLED OUT OF HOLE TEST STRING. BROKE OUT SUBSEA LUBRICATOR VALVE	2
	1640	BROKE OUT SUBSEA TEST TREE AND RACKED IN DERRICK ENDING DST #5A	3
10APR86		REPLACED DAMAGE BALL AND SEATED ASSY IN SUBSEA LUBRICATOR VALVE	4
	1355	MADE UP SUBSEA TEST TREE AND RAN IN HOLE. STARTED DST #6	5
	1540	RIGGED UP SURFACE LINES AND EQUIPMENT	6
	1608	PRESSURE TESTED TUBING AT 5000 PSI	7
	1650	PRESSURE TESTED SURFACE LINES AND CHOKE MANIFOLD AT 5000 PSI	8
	1728	OTIS WIRELINE RAN IN HOLE 2-1/8 INCH GAUGE RING	9
	1900	RIGGED UP SCHLUMBERGER LUBRICATOR	10
	1935	PRESSURE TESTED LUBRICATOR AT 5000 PSI	11
	2000	DISPLACED TEST STRING WITH NITROGEN	12
	2127	BLD DOWN TEST STRING PRESSURE TO 1250 PSI	13
	2150	OPENED LPR-N TESTER VALVE	14
	2400	SCHLUMBERGER RAN IN HOLE TO PERFORATE	15
11APR86	0126	SCHLUMBERGER PERFORATED INTERVAL 2786-2790 METRES	16
		STARTED DST #6 (SEE FIELD REDINGS)	17
12APR86	0932	SHEARED LPR-M2 AND REVERSED OUT TEST STRING	18
	1400	RIGGED DOWN SURFACE EQUIPMENT	19