

450141

PRELIMINARY SIDE WALL CORE SUMMARY BY EXLOG

WELL: PELICAN NO.5

AMOCO AUSTRALIA PETROLEUM CO.

MARCH 2-5, 1986

RUN 1

| DEPTH METERS | RECOVERY CM. | SUMMARY DESCRIPTION |
|-----------------|-----------------|------------------------|
| 4255.0 | 2.5 | ARGILLACEOUS SANDSTONE |
| 4247.0 | BROKEN | SILTY CLAYSTONE |
| 4216.0 | BROKEN | SHALE |
| 4162.0 | BROKEN | ARGILLACEOUS SANDSTONE |
| 4120.0 | MISSING | |
| 4107.0 | MISSING | |
| 4076.2 | BROKEN | SANDSTONE |
| 4048.7 | EMPTY | |
| 4013.5 | MISSING | |
| 3998.2 | 1.5 | ARGILLACEOUS SANDSTONE |
| 3976.5 | BROKEN | SILTY CLAYSTONE |
| 3928.5 | BROKEN | |
| 3903.8 | EMPTY | SANDSTONE |
| 3891.5 | BROKEN | SILTSTONE |
| 3836.5 | BROKEN | SANDSTONE |
| 3774.5 | BROKEN | SILTY SANDSTONE |
| 3716.5 | BROKEN | SILTY SANDSTONE+COAL |
| 3697.0 | BROKEN | SILTY SANDSTONE |
| 3684.0 | 1.0 | SANDY SILTSTONE |
| 3667.5 | BROKEN | SILTSTONE |
| 3653.0 | BROKEN | ARGILLACEOUS SANDSTONE |