

## PRELIMINARY SIDEWALL CORE SUMMARY BY EXLOG

WELL: PELICAN NO.5

AMOCO AUSTRALIA PETROLEUM CO.

MARCH 2-5, 1986

RUN 2

DEPTH METERS	RECOVERY CM.	SUMMARY DESCRIPTION
4236.5	BROKEN	ARGILLACEOUS SANDSTONE
4213.2	EMPTY	
4203.7	EMPTY	
4170.6	BROKEN	SANDSTONE
4154.7	BROKEN	SILTY SANDSTONE
4130.0	BROKEN	SILTY CLAYSTONE
4113.0	BROKEN	ARGILLACEOUS SANDSTONE
4087.6	MISSING	
4085.0	BROKEN	CLAYSTONE
4071.6	1.0	SANDSTONE
4057.0	0.7	SILTSTONE
4034.2	1.0	ARGILLACEOUS SANDSTONE
4016.2	BROKEN	SANDSTONE
4010.2	BROKEN	ARGILLACEOUS SANDSTONE
4005.0	EMPTY	
3995.5	MISSING	
3989.5	BROKEN	SANDSTONE
3941.0	BROKEN	CLAYSTONE
3937.1	1.0	SILTY SANDSTONE
3910.5	EMPTY	
3807.0	1.5	CLAYSTONE