

## PRELIMINARY SIDE WALL CORE SUMMARY BY EXLOG

WELL: PELICAN NO.5

AMOCO AUSTRALIA PETROLEUM CO.

MARCH 2-5, 1986

RUN 3

DEPTH METERS	RECOVERY CM.	SUMMARY DESCRIPTION
4106.5	BROKEN	CLAYSTONE
4012.5	EMPTY	
4005.0	1.0	SANDSTONE
3995.0	BROKEN	ARGILLACEOUS SANDSTONE
3903.0	BROKEN	CARBONACEOUS SANDSTONE
3900.5	BROKEN	ARGILLACEOUS SANDSTONE
3895.5	BROKEN	ARGILLACEOUS SANDSTONE
3875.0	BROKEN	SILTY SANDSTONE
3846.0	1.3	CLAYSTONE & COAL
3810.5	BROKEN	ARGILLACEOUS SILTSTONE
3778.0	BROKEN	SILTY SANDSTONE
3741.0	1.5	SILTY CLAYSTONE
3726.0	BROKEN	CLAYSTONE
3710.0	BROKEN	BROKEN
3700.0	MISSING	
3692.5	1.5	ARGILLACEOUS SANDSTONE
3688.0	0.5	ARGILLACEOUS SANDSTONE
3679.5	EMPTY	
3673.0	BROKEN	SILTY SANDSTONE
3663.5	1.5	ARGILLACEOUS SANDSTONE
3660.0	MISSING	