LOG-LOG-SB | DEPTH 1 : SCALE 1/500

CSU

COMPANY: WORCE AUSTRALIA
WELL: CAPE CHERILL NO. 1
FIELD: KILBURY
DATUM: SEABASE
LOCATION: 1000m N
LOCATION: 1000m WESTERLY THOMSON
RUN: ONE
LOCATION: 1000 FR SO SEA &
1000 FR WE SEA & 1000 FR
PERMANENT DATUM: M.S.L. ELEVATIONS:
LOG MEASURED FROM: K.B. 25.0 M ABOVE PERM. DATUM
DRILL MEASURED FROM: K.B. G.L. 16.0 M

DATE: 21 NOV 80
RUN NO: ONE

BOTTOM DRILLER: 4000.0 m
BOTTOM LOGGED: 4000.0 m
TOP LOG INTERVAL: 1000.0 m
CASING DRILLER: 1000 m
CASING LOGGED: 1000 m
TYPE FLUID IN HOLE: SEAWATER GEL POLYMER
DENSITY: 1.14 g/cc
PH: 10.5
FLUID LOSS: 4.2 cc
SOURCE OF SAMPLE: FLOWLINE
RM @ MEAS TEMP: 0.180 OHMM @ 20.0 DEGF
RMF @ MEAS TEMP: 0.160 OHMM @ 20.0 DEGF
RMC @ MEAS TEMP: 0.220 OHMM @ 20.0 DEGF
RM @ BHT: 0.080 OHMM @ 210. DEGF
RMF @ BHT: 0.060 OHMM @ 210. DEGF
TIME CIRC STOPPED: 0200 HR
TIME LOGGER ON BTM.: 0700 HR
MAX. REC. TEMP.: 210.0 DEGF
EQUIPMENT NUMBER: 3
LOCATION: 3KIL
RECORDED BY: S. MITCHELM SMILLS
WITNESSED BY:

REMARKS:

CALIBRATION SUMMARY:
BHC @ 0115 HRS 0700 HRS DNC @ 0300 PNC 0715

THE INTERPRETATION OF ANY OF THE RESULTS OF THIS SURVEY IS A MATTER OF OPINION AND THEREFORE WE CANNOT GUARANTEE THE ACCURACY OR CORRECTNESS OF ANY INTERPRETATION, AND WE SHALL NOT BE LIABLE OR RESPONSIBLE FOR ANY LOSS, COSTS, DAMAGES OR EXPENSES INCURRED OR SUSTAINED BY ANYONE RESULTING FROM ANY INTERPRETATION MADE BY ANY OF OUR OFFICERS, AGENTS OR EMPLOYEES. THESE INTERPRETATIONS ARE ALSO SUBJECT TO OUR GENERAL TERMS AND CONDITIONS AS ACCEPTED AT THE TIME OF CONTRACT.

FILE 1

			4.0000
		PEF	4.00
K.H			14.540
K.HOU			14.139
			4.0000

FILE 2

			4.0000
		PEF	4.00
K.H			14.540
K.HOU			14.139
			4.0000

SONIC SEISMIC RIGHT TO TENSION REFERENCE POINT

DEPTH	0.0	DEPTH	0.0
DEPTH	0.0	DEPTH	0.0
DEPTH	0.0	DEPTH	0.0
DEPTH	0.0	DEPTH	0.0
DEPTH	0.0	DEPTH	0.0
DEPTH	0.0	DEPTH	0.0
DEPTH	0.0	DEPTH	0.0
DEPTH	0.0	DEPTH	0.0

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT

LOG-LOG-SB | DEPTH 1 : SCALE 1/500

CSU