
COMPANY ESSO EXPLORATION AUST. INC.
WELL BARRACOUTA A1
FIELD
COUNTY AUSTRALIA STATE VICTORIA
DOUBLE COMPENSATED SONIC LOG - GAMMA RAY
GAMMA RAY
CALIPER
INTERVAL TRANSIT TIME
STATISTICAL VARIATIONS
40 Log Swds. and T.C.
DOWN HOLE CALIBRATION AFTER SURVEY
CALIBRATION FILMS
DOWN HOLE CALIBRATION BEFORE SURVEY