

1/4 Survey day \$1250.00

1/4 Field Assist. day \$180.00

12-12-99 Returned to the site and continued reading the Z component. It rained heavily throughout the day. We finished the Z by 3:00 pm and packed up the gear by 5:00 pm.

SURVEY PARAMETERS:

Loop#1 : 600 x 500m

380900E; 5359170N; 380900E; 5358700N;

381300E; 5358700N; 381400E; 5359170N

Current : 13Amps

Time Base : 20.0ms

Ramp Time : 1.0ms

Sync : Cable

Hole No. : SHD-21

380890E; 5358890N

Depth : 850m

Channels : 31

Components : Z

1/4 Survey day \$1250.00

1/4 Field Assist. day \$180.00

13-12-99 Completed reading the X-Y on loop #1, packed up the gear and weathershed by 2:00 pm. (Goldfields have kindly given permission for us to go to another client to complete some urgent work and return later).

SURVEY PARAMETERS:

Loop#1 : 600 x 500m

380900E; 5359170N; 380900E; 5358700N;

381300E; 5358700N; 381400E; 5359170N

Current : 13Amps

Time Base : 20.0ms

Ramp Time : 1.0ms

Sync : Cable

Hole No. : SHD-21

380890E; 5358890N

Depth : 850m

Channels : 31

Components : XZ

1/4 Survey day \$625.00

1/4 Field Assist. day \$90.00

1/4 Mob. day N/C

22-1-00 Met up with Scott and Dale at 7:30am and drove out to South Henry. The weather today was particularly bad and we had to call it a