

**Appendix 2 Rehabilitation photos**



22PPRC001 looking SW



22PPRC002 looking SW



22PPRC003 looking NW



22PPRC003 access blocked at road



22PPRC004 looking W



22PPRC005 looking NE



22PPRC006 looking NE



22PPRC007 looking NE. Drilled on existing track.



22PPRC008 looking NE. Drilled on existing track.



22PPRC009 looking NE. Drilled on existing cleared area.



22PPRC010 looking SW.



22PPRC011 looking SW.



22PPRC012 looking SW.



22PPRC013 looking SW.



22PPRC014 looking SW.



22PPRC015 looking NE.



22PPRC016 looking SW.



22PPRC017 looking E.



22PPRC018 looking W.



22PPRC019 looking E.



22PPRC020 looking W.



22PPRC021 drilled on road, looking N.



22PPRC022 looking E.



Track to 22PPRC006 looking W.



Track to 22PPRC011 to 22PPRC012 looking NE



Track to 22PPRC022 looking E.