

PD83 JC-11

<u>From (m)</u>	<u>To (m)</u>	
0	5.5m	River gravel, mainly cobble size, minor boulders
5.5	8.0	Arenite, lithic, medium grained, moderately weathered.
		EOH

Comments

- (i) Base of oxidation not determined.
- (ii) Abundant water flow from very shallow water table caused problems in seating the PVC casing to 5m; the hole was abandoned when the combined effects of high water flow in unconsolidated gravels caused the casing to shatter.