



5m contour interval

Compiled by: Associated Surveys (Vic.) Pty. Ltd.
 25 Burwood Road HAWTHORN 3122.
 (03) 818 7957, 819 4090.

Date of Photography - 5.2.1982

N.B. Broken contours (form lines) and italic spot heights indicate lesser reliability due to dense vegetation.

ELECTROLYTIC ZINC CO. OF ASIA LTD.
 PROJECT: MONTEZUMA JOINT VENTURE



SCALE: 1:5000	Survey:	Revised:
Reference:	Date:	30C
Drawn:	Checked:	

PROJ. 94-3-1029
 RE. 15/7/78
 E. Z. CO. SURVEYS
 HAWTHORN