

11002

TASMANIAN CONSTRUCTION MATERIALS REGISTER

780699

Quadrangle: (Flinders Is) Serial No: 5 Universal grid reference: IER 780706

Name of Owner: Council "Pitford Hill" pit

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable)

Past production: 100x50x5 = 25000 m³ Estimated reserves:

Description of site: Kullerup Rd, Dalana Rd photo 6/23

Limits to expansion:

Thickness of overburden: 3m

Sources of information: Field DM (VMT) Laboratory

Sizing Analysis:

a	3"	2"	1½"	1"	¾"	⅜"	3/16"	7	14	25	36	52	100	200	400
b	76.2	50.8	38.1	25.4	19.0	9.52	4.76	2.41	1.20	0.60	0.42	0.30	0.15	0.076	0.038
1						100	99	89			34			7	
2						0	1	11			66			83	
3						0	1	10			55			17	
4															

a: B.S.S. (Imperial) Screen size b: metric equivalents

L.L: 19 P.I: 8 L.S: 4 D.R: 50

Special tests:

Group Symbol (unified soil classification system): SM-SC

History:

Remarks: cemented granitic pit

M 1324

