

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 09001 Grid Reference YA 383603 Map Sheet No. 76171

Name of Owner/Quarry: DMR / PEARSHADE

Working Pit/Disused Pit/New Locality: _____

Past Production: 400 x 4 480 000³ Estimated Reserves: large

Description of site: _____

Limits to expansion: nil

Thickness of overburden: nil

Sources of information: _____ Field: Dau/Wmt Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: 19.1.80

| | | | | | | | | | | | | | | | |
|----|------|------|------|------|------|------|------|------|------|------|-------|------|------|-------|-------|
| mm | 76.2 | 50.8 | 38.1 | 25.4 | 19.0 | 9.53 | 4.76 | 2.36 | 1.18 | 0.60 | 0.425 | 0.30 | 0.15 | 0.075 | 0.038 |
| | 75.0 | 53.0 | 37.5 | 26.5 | | | | | | | | | | | |
| 1 | | | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | |

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: L. Pale little more on the island

History: on the main road pits on the island

Remarks: _____