

TASMANIAN CONSTRUCTION MATERIALS REGISTER

281587

Quadrangle: *80* Serial No: *9* Co-ordinates: KmN KmE

Name of Owner: *H.F.C.*

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable).

Past Production: *50x50x1M³* Estimated Reserves: *Equal*

Description of site: *North roadside, Gordon River Road*

Limits to expansion: *S. Road. W. Creek Bed*

Thickness of overburden: *5cm topsoil*

Sources of information: Field *WB 29.11.77* Laboratory

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L: P.I: L.S: D.R:.....

Special Tests:

Group Symbol (unified soil classification system):

Geological Description: *Quartz pebbles, sand and cobbles*

History: *Probably used to build up road banks over the creek.*

Remarks: *Used as a picnic ground until recently. Attempts being made to revegetate this pit.*