

TASMANIAN CONSTRUCTION MATERIALS REGISTER

302572

Quadrangle: *80* Serial No: *10* Co-ordinates: ..... KmN..... KmE

Name of Owner: *H.E.C.*

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable).

Past Production: *20x10x2m<sup>3</sup>* Estimated Reserves: *Equal?*

Description of site: *West Roadside, Gordon River Road*

Limits to expansion: *E. Roadside*

Thickness of overburden: *5cm soil*

Sources of information: Field *WD 29.11.77* Laboratory

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L: ..... P.I: ..... L.S: ..... D.R:.....

Special Tests: .....

Group Symbol (unified soil classification system): .....

Geological Description: *Mudstone Gravel*

History: *Probably used in causeway construction in the Hermit Valley area*

Remarks: *Disused for a long time.*