

TASMANIAN CONSTRUCTION MATERIALS REGISTER

376554

Quadrangle: 80 Serial No: 13 Co-ordinates: KmN..... KmE

Name of Owner: H.E.C.

Working Pit / Disused Pit / New Locality: (Delete whichever inapplicable).

Past Production: 100x20x3m³ Estimated Reserves: NIL

Description of site: East Roadside, Gordon River Road.

Limits to expansion: W. Road. Bedrock

Thickness of overburden: Material extends to the surface

Sources of information: Field WB 29.11.77 Laboratory

Sizing Analysis:

mm	75.0	53.0	37.5	26.5	19.0	9.51	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L: P.I: L.S: D.R:.....

Special Tests:

Group Symbol (unified soil classification system):

Geological Description: Granite or quartz ~~PC compliance~~

History:

Remarks: All the useful material has ~~been~~ seen removed or has since washed away.
There will be problem revegetating this pit.