

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 1 Grid Reference 220 448 Map Sheet No 82

Name of Owner/Quarry: _____

Working Pit/Disused Pit/New Locality: Occasionally worked on a small scale

Past Production: 15,000 m³ Estimated Reserves: Moderate

Description of site: Immediately to the East of Summerless Road,

In open eucalypt forest

Limits to expansion: None apparent

Thickness of overburden: 50 cm moderate coloured soils

Sources of information: RAAM Field: 30/11/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

90 Passing

mm	76.2	50.8	38.1	25.4	15.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1				<u>100</u>	<u>84</u>	<u>74</u>	<u>55</u>	<u>36</u>	<u>18</u>	<u>8</u>		<u>4</u>	<u>2</u>	<u>1</u>	
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GP

Geological Description: Weathered dolerite. Weathering

attack concentrated along joints has produced many, some
large (3m³) rounded boulder. Though these are also easily broken
but and clay concentrations moderately high.

History: _____

Early use by Kingborough Council.

Remarks: Averaged dimensions 110x30x4.5