

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 2 Grid Reference 258 427 Map Sheet No 82

Name of Owner/Quarry: Kingborough Council.

Working Pit/Disused Pit/New Locality: Not worked on any scale for several yrs.

Past Production: 18,000 m³ Estimated Reserves: small-moderate.

Description of site: Quarry (single bench at road level) - 500m along
Proctora road from its Rhannel Hwy junction. Set into moderately sloping lightly
timbered hill.

Limits to expansion: None visible above main face.

Thickness of overburden: 20-40 cm. clayey yellow-brown soil.

Sources of information: RAAM Field: 9/11/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): GP.

Geological Description: Decomposed dolerite - Fill material with
many large sub-rounded boulders.

History: Kingborough Council Pit. - finished

Remarks: Averaged dimensions - 50x60x6