

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 5 Grid Reference 251 488 Map Sheet No 82

Name of Owner/Quarry: M. Bain - Proctors Saddle

~~Working Pit~~/Disused Pit/~~New~~ Locality: Little use

Past Production: 132,000 Estimated Reserves: Moderate.

Description of site: Large Quarry on the western side of the Outlet

Limits to expansion: Outlet to the east.

Thickness of overburden: shallow soil.

Sources of information: RAAM. Field: 7/12/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	15.0	11.8	7.6	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1					100	54	23	13					3			1	
2					100	65	34	19					7			4	
3																	
4																	

L.L. _____ P.I. N.P. L.S. _____ D.R. .33/.57.

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Grange Mudstone, partially metamorphosed by a transgressive detrital silt (in the eastern half of the quarry). Siltstone is somewhat calcareous.

History: _____

Remarks: Averaged Dimensions: 110x120 x 10.

There are minor unaltered shale beds that are a source of clay fines, the rock splits along bedding planes.