

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 6 Grid Reference 252 447 Map Sheet No 82

Name of Owner/Quarry: _____

Working Pit/Disused Pit/New Locality: Not worked 5 yrs +

Past Production: 6,000 m³ Estimated Reserves: Small.

Description of site: Pit on S.W. side of Proctora Road and Vincenta bk.
50 M West of the Southern Outlet. Modeste - steep land. Light pinkish sand.

Limits to expansion: None behind face.

Thickness of overburden: 10 cm of infertile soil

Sources of information: RTAM Field: 9/11/78 Laboratory: PWD. Ref. No.: _____

Sizing analysis: _____ Date: _____

% Passing

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1					<u>100</u>	<u>95</u>	<u>73</u>	<u>47</u>			<u>17</u>			<u>16</u>	
2															
3															
4															

L.L. 43 P.I. 22 L.S. 9 D.R. 47

Special tests: _____

Group Symbol (unified soil classification system): GW-GM.

Geological Description: In situ and down slope deposit of siltstone gravel and silt.

History: A Little used on the Southern Express way - last time used.

Remarks: Averaged dimensions of pit 70 x 25 x 35 m.