

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 7 Grid Reference 260434 Map Sheet No 82

Name of Owner/Quarry: I.M. Bones.

~~Working Pit/Disused Pit/New~~ Locality: not worked 6 years +.

Past Production: 6,500 Estimated Reserves: Moderate (low grade)

Description of site: Scrappings in bush land about 1km up  
steepish track from Proctora Road.

Limits to expansion: No physical constraints visible, <sup>environmental?</sup> though maybe some <sup>mining</sup>

Thickness of overburden: Material used from surface.

Sources of information: RAAM Field: 9/11/78 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1		100	88	83	75	53	39	32			24			17	
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): GC.

Geological Description: Recomposed dolerite ⇒ boulders (spheroid-  
ally weathered) grit and clay.

History: \_\_\_\_\_

Remarks: Adhoc diggings of very poor material.  
Averaged (approx.) dimensions 50x50x25 m.