

10c J 82/10

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 10c Grid Reference 089 615 Map Sheet No 82

Name of Owner/Quarry: George Johnson - Malbina.

~~Working Pit/Disused Pit/New~~ Locality: As for 10b

Past Production: 1050 m³ Estimated Reserves: Very small.

Description of site: Very similar pit to 10b, slightly smaller, same aspect etc

Limits to expansion: as for 10b

Thickness of overburden: " " "

Sources of information: RAAM Field: 8/12/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	15.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SM-GM

Geological Description: Angular silty fine gravel. Coarse material in eastern half of pit.

History: _____

Remarks: 25 x 60 x .6 + 150m³.