

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 17 Grid Reference 398978 Map Sheet No 82

Name of Owner/Quarry: Tasmanian Finance Agency - Droughty Point

Working Pit/Disused Pit/New Locality: D.

Past Production: 2000 Estimated Reserves: m

Description of site: at top Droughty hill in serrated
turnoff area.

Limits to expansion: property fences, environmental considerations

Thickness of overburden: 1/2 metre

Sources of information: PR/MW Field: 12/12/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: weathered dolerite. => gravel with a few large dolerite boulders.

History: _____

Remarks: large amounts stockpiled